

Strainert Load Pin Sensor Troubleshooting Guide



Strainsert Load Pin Sensor Troubleshooting Guide

PHYSICAL INSPECTION

1. Inspect the sensor for physical damage, cracks bending, distortion, corrosion, etc.
2. Inspect connector and receptacle pins and sockets for damage (loose or bent) or contamination from debris or moisture.
3. Inspect cable thoroughly for damage, such as cuts, nicks, bent, or pinched wiring. A cable bend greater than 60° could cause short readings.
4. Verify good connections at any intermediate wire terminations between the load sensor and facility instrumentation.

ZERO LOAD MEASUREMENT (Use Existing DAQ or Strain Meter)

1. Observe the load pin bridge readings while under no load. If the load is drifting or the unloaded readings are greater than 5% of the full-scale output, this may indicate a problem with the sensor. Please note this “zero” magnitude can change slowly over time and is normal in strain gage bridges.

FOR NON-AMPLIFIED SENSORS

BRIDGE RESISTANCE MEASUREMENT (Using a Digital Multimeter)

1. Disconnect all Load Pin cable wires at instrumentation termination point.
2. Set the Digital Multimeter (DMM) to measure “Ohms”.
3. With the DMM, measure and record resistance readings using the pin assignments provided in the customer wiring diagram or control drawing in accordance with Table 1:

Standard Single / Dual / Bi-Axial Bridge Description for Cable Wire Colors Resistance, Ohms
(For Custom Wiring see your data package for all Bridge Connections)

Table 1

| Description | Standard Connector Pins | Standard Cable Wire Colors | Nominal Resistance (Ohms) ±9 ohms |
|----------------------------------|-------------------------|----------------------------|--------------------------------------|
| Standard Single Bridge: | | | |
| Excitation (+) / Excitation (-) | A / D | Red / Black | 350(*) |
| Signal (+) / Signal (-) | B / C | Green / White | 350 |
| Excitation (+) / Signal (+) | A / B | Red / Green | 265 |
| Excitation (+) / Signal (-) | A / C | Red / White | 265 |
| Excitation (-) / Signal (+) | D / B | Black / Green | 265 |
| Excitation (-) / Signal (-) | D / C | Black / White | 265 |
| Standard Dual / Bi-Axial Bridge: | | | |
| Excitation (+) / Excitation (-) | E / H | Blue / Brown | 350(*) |
| Signal (+) / Signal (-) | F / G | Orange / Yellow | 350 |
| Excitation (+) / Signal (+) | E / F | Blue / Orange | 265 |
| Excitation (+) / Signal (-) | E / G | Blue / Yellow | 265 |
| Excitation (-) / Signal (+) | H / F | Brown / Orange | 265 |
| Excitation (-) / Signal (-) | H / G | Brown / Yellow | 265 |

(*) Actual value may be as high as 15% above the nominal value due to signal trim, compensation resistors and cable resistance.

4. Repeat Step 1 – Step 3 for bridge 2 when applicable.

LOAD PIN RAW OUTPUT SIGNAL MEASUREMENT (Using a Power Supply and Digital Multimeter)

1. Measurements are independent of customer strain meter / DAQ.
2. Connect the E+ and E- cable leads to a power supply providing between 5-12 Volts DC.
3. Connect the S+ and S- cable leads to a DMM and set to measure either DC Volts or DC mV (if equipped). Recommended measurement range to be in millivolts.
4. Standard cable color and hook ups are provided in the Table 2 below. For custom applications, please review your data package for Custom Wiring Diagrams or Control Drawings.

Standard Single Bridge Description for Pinout and Cable Colors

(For Dual Bridge / Bi-Axial / Custom Wiring see your data package for all Bridge Connections)

Table 2.

| Standard Cable Color | Standard Connector Pin Out | Function | Bridge Number |
|----------------------|----------------------------|----------------|---------------|
| Red / Blue | A / E | Excitation (+) | 1 / 2(*) |
| Green / Orange | B / F | Signal (+) | 1 / 2(*) |
| White / Yellow | C / G | Signal (-) | 1 / 2(*) |
| Black / Brown | D / H | Excitation (-) | 1 / 2(*) |

(*) When option is available.

5. Power on power supply to provide voltage across E+ and E-.
6. Measure and record load pin sensor output signal (mV) between S- and S+ under no-load condition.
7. Apply a load to the sensor then repeat measurement.
8. Using the offset recorded in Step 6, compare output to calibration data (mV/V vs. Engineering Units)
9. See Strainsert Calibration Certificate for comparison.
10. Calibration certificates are available on the Strainsert website
<https://www.strainsert.com/services/online-calibration-certificate-lookup-tool/>
11. For dual bridge and bi-axial load pin sensors repeat Steps 2 through 10 for bridge 2 if applicable.

LOAD PIN INSULATION RESISTANCE (IR) MEASUREMENT (Using a Megohm Insulation Tester)

1. Connect all load pin sensor wire leads to the positive side (+) lead of the insulation tester.
2. Connect negative (-) insulation tester lead to a secure point on the load pin sensor body.
3. Set insulation test voltage to 50V (maximum)
Warning: Insulation test voltages that exceed 50 Volts between the sensor wires and/or sensor body can cause permanent damage to the internal strain gages and will void the manufacturer's warranty.
4. Initiate the test using the insulation meter test button.
5. Verify measurement is nominally greater than 5 Giga-ohms.
6. If test value is less than 5 Giga-ohm contact Strainsert.
7. For dual bridge repeat Steps 1 – Step 5 for each bridge.
8. **Bridge to Bridge (IR):** For dual bridge and bi-axial load pin sensors, connect bridge 1 load pin sensor wire leads to the positive side (+) lead of the insulation tester. Connect bridge 2 load pin sensor leads to the negative (-) insulation tester leads.
9. Repeat Step 5 through Step 7.

FOR 2-WIRE AMPLIFIED LOAD PIN SENSORS (ONLY)

LOAD PIN AMPLIFIED OUTPUT MEASUREMENT (4 to 20 mA)

1. Connect positive side of the power supply per Table 3.
2. Connect the negative side of the power supply to a load resistor (typically 250 Ohms).
3. Connect the opposite side of the load resistor to the return wire per Table 3.
4. Connect a DMM across the load resistor per the drawing below. Set the DMM to measure DC Volts.
5. Standard cable color and hook ups are provided in the table below. For custom applications, please review your data package for Custom Wiring Diagrams or Control Drawings.




Table 3.

| Standard Cable Color | Standard Connector Pin Out | Function | Bridge Number |
|----------------------|----------------------------|-----------------|---------------|
| Red | A (13-28 Volt) | 13-28 VDC Power | 1 |
| Black | D (Return) | Power Return | 1 |
| Green | B (13-28 Volt) | 13-28 VDC Power | 2(*) |
| White | C (Return) | Power Return | 2(*) |

(*) When option is available.

6. Power on power supply to provide current to the circuit.
7. Measure and record sensor output volts DC under no load condition. Zero load should be 1.00 Vdc +/- 50 mV nominal across a 250 Ohm load resistor.
8. Apply a load to the sensor then repeat measurement.
9. Using recorded zero load offset from Step 7, compare output to the calibration data (Volts DC vs. Engineering Units)
10. See Strainsert Calibration Certificate for comparison.
11. Calibration certificates are available on the Strainsert website
<https://www.strainsert.com/services/online-calibration-certificate-lookup-tool/>
12. For dual bridge and bi-axial load pin sensors repeat Steps 1 through 11 for bridge 2 if applicable.

2-WIRE LOAD PIN INSULATION RESISTANCE MEASUREMENT (ONLY) (Using a Megohm R Tester)

1. Connect all load pin sensor wire leads to the positive side (+) lead of the insulation tester.
2. Connect negative (-) insulation tester lead to a secure point on the load pin sensor body.
3. Set insulation test voltage to 50V (maximum)

Warning: Insulation test voltages that exceed 50 Volts between the sensor wires and/or sensor body can cause permanent damage to the internal strain gages and void the manufacturer's warranty.

4. Initiate the test using the insulation meter test button.
5. Verify measurement is nominally greater than 5 Giga-ohm's.
6. If test value is less than 5 Giga-ohm contact Strainsert.
7. For dual bridge and bi-axial load pin sensors, connect bridge 1 load pin sensor wire leads to the positive side (+) lead of the insulation tester. Connect bridge 2 load pin sensor leads to the negative (-) insulation tester leads.
8. Repeat Step 4 through Step 6.

| Problem | Possible Cause | Possible Solution |
|---|---|--|
| Load readings are low or do not increase with applied load | Pin is misaligned to Calibration Line | Align Pin per the Customer Control Drawing |
| | Pin is not installed correctly and not deflecting | Rotate the pin about 90 degrees. Check that groove position allows for pin deflections |
| | Damaged or disconnected cable | Inspect cable for damage and reconnect/repair as needed. |
| Load readings are saturated or opposite polarity to what is expected | Installed upside-down | If the load appears to have opposite polarity, rotate the pin 180 degrees. |
| | Wiring connection swapped | Inspect cable and wiring for proper connections and reconnect, as required. |
| Load readings do not match calibration data sheet | Scaling in instrument is incorrect | Adjust instrument scaling to match calibration certificate |
| | Load Distribution is significantly different from the factory calibration | Conduct an in-place calibration or proof load to obtain new scaling per in-place applied load |
| | Wiring connected improperly | Inspect cable and wiring for proper connections and reconnect, as required. |
| (High Zero Reading) No load readings >5% of full scale | Shift due to overload | Factory repair/replacement |
| | Instrumentation offset or Tare has shifted | Investigate software, meter, display, etc. offset value |
| | Insulation Resistance Short | Return to manufacturer for evaluation and repair. |
| (Zero Reading Shift) No load readings < 5% full scale | Strain gage shift over time | This is a phenomenon of strain gage circuits, and this initial offset can be zeroed out on instrumentation without effecting the transducer span |
| Bridge Resistance readings are outside of tolerances | Broken pin, broken connection, moisture in connector or receptacle, open gage circuit | Return to manufacturer for evaluation and repair. |
| Readings are slightly drifting with no load applied | Heating on one side of transducer | Possible temperature gradients due to non-uniform temperature across load pin sensor body. |
| | Loose or cold solder connections inside bridge circuit. | Return to manufacturer for evaluation and repair. |
| | Internal damage to strain gage circuit. | |