




# ACCURACY

*Strain Gages directly bonded to neutral axis demonstrate increased insensitivity to extraneous loading*



*Pressure Compensation Designs*

