


## Full Bridge

## Trim & Compensation Resistance

## Header Identification Code



HEADER FRONT VIEW

Legend:

Strain Gages: G1, G2, G3, and G4

Excitation: E+ and E-Signal: S+ and S-

Bridge Trim & Compensation Resistors when required, as follows:

Initial Bridge Balance: R1a or R1b

Signal Trim: R2 Modulus Trim: R3

Temperature Compensation: R4a or R4b

Excitation Res. Trim: R5 Signal Res. Trim: R6

(Applicable notation and codes conform to Western Regional Strain Gage Committee's recommendations.)

Note: Increasing tension strain in gages G1 and G3, and compression in gages G2 and G4, induces increasing signal of positive polarity.