



**FORM S-113B**

**Legend**

<b>Strain Gages:</b>	G1, G2, G3, and G4
<b>Excitation:</b>	E+, and E-
<b>Signal:</b>	S+ and S-

**Bridge Trim & Compensation Resistors when required, as follows:**

<b>Input Bridge Balance:</b>	R1a or R1b	<b>Temp. Compensation:</b>	R4a or R4b
<b>Signal Trim:</b>	R2	<b>Modulus Trim:</b>	R3
<b>Excitation Res. Trim:</b>	R5	<b>Shunt Resistor:</b>	R-CAL

(Applicable notations and codes conform to Western Regional Strain Gage Committee's recommendation.)  
 Note: Increasing tension strain in gages G1 and G3, and compression in gages G2 and G4, induces increasing signal of positive polarity.

(\*) For MqT4 cable color code is yellow.