


Quarter Bridge



Legend:

Excitation: E+ and E-
 Signal: S+ and S-
 R_m : Matched Resistors
 R_{dg} : Dummy Gage Resistor

Diagram applies to Type-W, as shown, provided the red lead is connected to E+.

(Applicable notation and codes conform to Western Regional Strain Gage Committee's recommendations.)

Note: Increasing tension strain in gages induces increasing signal of positive polarity.