



FORM S-112A

Note: Increasing tension strain in gages induces an increasing signal of positive polarity.

Special strain gage with half the grid installed 180° opposite the other half minimizes stray bending effects.